



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)
T.R. PATTINAM - 609606, KARAIKAL.



Phone No: 04368- 233060

E-Mail : ppclmmc@gmail.com

Fax: 04368 - 233355

Our GSTIN No.: 34AAACP6507E1ZS

Ref. No: V-066/MMC/2021-22/ 705

Dt. 18.08.2021

ENQUIRY

To

As per list enclosed.

Sub: Inviting offer for Instrument Air compressor 'B' corroded pipeline inlet /outlet replacement and repair work - Reg.

QUOTATION TO BE:

Submitted on or before 08.09.2021 - 12.00 Noon	Opened on 09.09.2021 -03.00PM
Kept valid upto three months	Submitted in ONE Part.

Sealed quotations are invited for Instrument Air compressor 'B' corroded pipeline inlet /outlet replacement and repair work as per the scope of work furnished in the annexure and as per our terms and conditions mentioned therein.

TERMS AND CONDITIONS:

1. The rate quoted should be inclusive of material, manpower mobilization and demobilization, tools and tackles, etc. required for the works, GST, EPF & ESI charges and other charges as admissible.
2. 100% Payment will be made within 30 days from the date of receipt of your invoice after completion of work satisfactorily and approval of Engineer-in-charge and after submission of EPF/ESI, etc. documents. Otherwise 80% payment will be made after completion of work satisfactorily and approval of Engineer-in-charge and the balance 20% payment will be made after submission of necessary EPF & ESI, etc. documents.
3. The bill in triplicate along with advance stamped receipt should be sent to the undersigned for effecting payment.
4. Necessary Gate pass should be obtained well before the commencement of work.
5. All the Safety Rules as per the Factory Act 1948, Puducherry Factory Rule and PPCL Safety instructions to be strictly followed inside the plant area.
6. In case of any faulty workmanship in the scope of work, the tenderer must rectify the same.



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)

T.R. PATTINAM - 609606, KARAIKAL.

Phone No:04368- 233060

E-Mail : ppclmmc@gmail.com

Fax: 04368 - 233355.

Our GSTIN No.: 34AAACP6507E1ZS

Ref. No: V-066/MMC/2021-22/ 705

Dt. 18.08.2021

ENQUIRY PAGE NO. 2

7. The contractor should submit the following:

For EPF:

To be generated from the EPF website for the specific month for the manpower deployed to PPCL and the same to be enclosed separately with a covering letter.

i) Combined challan of account no. 01,02,10,21 & 22 with TRRN number.

ii) EPF - Electronic Challan cum Return (ECR) iii) EPF Challan summary/ EPF - TRRN details

For ESI:

To be generated from the ESI website for the specific month for the manpower deployed to PPCL and the same to be enclosed separately with a covering letter.

i) ESI challan number ii) ESI monthly contribution- online challan status (Transaction details)

iii) ESI monthly contribution details (contractor wise) for the month of.....

And other records to be submitted along with the above:


Copy of register of wages for the persons deployed to PPCL duly attested by the contractor.

Copy of register of muster roll/attendance for the persons deployed to PPCL duly attested by the contractor.

Copy of payment proof for the persons deployed to PPCL through bank duly attested by the contractor.

In addition to the above as a mandatory, the proposed parties/manpower supply contractors have to obtain the FORM-III -Registration certificate under Pondicherry shops and Establishment Rules 1964 as a Employer of the Establishment to be permitted to employ persons under their firm and also obtain Labour License under the contract labour (Regulation & Abolition act. 1970 with the labour Department, Government of Puducherry, Karaikal.

8. Our GSTIN No.: 34AAACP6507E1ZS registered with Commercial Taxes Department, Puducherry.
9. Sealed quotation should be super scribed as "QUOTATION / ENQUIRY NO. V-066 for Instrument Air compressor 'B' corroded pipeline inlet /outlet replacement and repair work - due on 08.09.2021".
10. Applicable other charges, if any should be clearly mentioned as whether inclusive or exclusive. If not mentioned, it will be presumed that the rate quoted is inclusive of all taxes other charges.
11. The party should submit two copies of photographs of all the employees deployed in PPCL for the above work for gate pass purpose. The name & photo of the employees should be attested by the contractor.
12. The undersigned reserves all rights to accept/reject any or all the quotations without assigning any reasons thereof.
13. The party should visit the site before quoting the offer.


19/08/2021

EXECUTIVE ENGINEER (MECH)-PLANT



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)

T.R. PATTINAM - 609606, KARAIKAL.

Phone No:04368- 233060

E-Mail : ppcimmc@gmail.com



Fax: 04368 - 233355.

Our GSTIN No.: 34AAACP6507E1ZS

Ref. No: V-066/MMC/2021-22/ 705

Dt. 18.08.2021

ANNEXURE PAGE No.1

SCOPE OF WORK FOR INSTRUMENT AIR COMPRESSOR-2 CORRODED PIPE LINE/COOLERS
END COVER REPAIR/REPLACEMENT WORK

1. Removing of Old corroded cooling water pipe lines from Instrument Air compressor as per the instruction of Engineer Incharge.
2. Pre fabrication of pipe line as per the existing piping layout and as per the instruction of Engineer incharge.
3. Installation of the newly fabricated pipe line and integration with the existing system compressor/pipe line at the appropriate point with tapings, pipe fittings and valves.
4. The new pipe line to be laid as per the existing pipe lay out and proper supports to be provided in the appropriate points.

INTER COOLER/AFTER COOLER END COVER REPAIR WORK.

5. The existing Inter coolers and after coolers end covers are to be dismantled from the compressor. The existing flanges have to be separated from the Dish ends without damaging the flanges.
6. The removed flanges to be machined / bored to suit the new MS pipe by PPCL.
7. New dish ends with given length of pipes has to be welded with old flanges.
8. MS Partition plate to be welded as per the existing system.
9. The flange faces to be machined after welding if any face out on gasket surface.
10. Cooling water inlet and out let pipe line tapings with flange joints has to be welded to suit the site condition.
11. Necessary safety precautions to be taken care for welding and cutting works.
12. Manpower, machineries, tools, tackles consumables to be arranged by the contractor.
13. The party should visit the site before quoting the rate.
14. Leak test to be carried out if any leakage is there, that is to be attended.
15. Metallic primer 1 coating and epoxy (color-Apple Green) painting 2 coating to be applied on outer surface.
16. The dimensions mentioned in the layout diagram are to be taken as approximate for estimation purpose only, but actual measurement will be taken at site during execution of work.

PPCL Scope

1. Welding electrodes, Paints, necessary pipes and fittings will be supplied by PPCL. Flange machining by PPCL.
2. Electricity and water will be provided by PPCL.

19/08/2021

EXECUTIVE ENGINEER (MECH)-PLANT



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)
T.R. PATTINAM - 609606, KARAIKAL.



Phone No:04368- 233060

E-Mail : ppclmmc@gmail.com

Fax: 04368 - 233355.

Our GSTIN No.: 34AAACP6507E1ZS

Ref. No: V-066/MMC/2021-22/705

Dt. 18.08.2021

ANNEXURE PAGE No.2

Name Of Work: Instrument Air compressor 'B' corroded pipeline inlet /outlet replacement and repair work at PPCL, T.R.Pattinam, Karaikal.

Sl.No.	Description	Amount in Rs.
1	Instrument Air compressor 'B' corroded pipeline inlet/outlet replacement and repair work (Scope of work as per annexure)	
	Gross Total	
	EPF & ESI Charges	Inclusive
	Sub Total	
	GST @ 18%	
	Net Total	
(Rupees)		

Payment Terms: As per Terms & Condition - 2

Validity: Your offer should be valid for 90 days from the date of tender opening.


Note: 1) The rates to be quoted in all the columns of the above schedule and no columns should be left blank, if any column is left blank then the offered quotation will not be considered.

2) The quoted schedule should be affixed by the company seal and signed by the concerned authority.

Name of the Company:

Company seal with Signature:

Instrument Air Compressor cooling water pipeline layout.



L - Blowdown
 T - Tee Joint
 F - Flange

All dimensions are in mm.

S.No.	Description	Qty
Pipe fittings Schedule 40. IS Std. Carbon steel / Forged steel.		
1.	2x1.5 inch socket weld unequal T	06 nos.
2.	1.5 inch socket weld equal T	04 nos.
3.	1.5 inch socket weld elbow	13 nos.
4.	4x3 inch concentric reducer	02 nos.
Flange: Carbon steel / Forged steel, ANSI B16.5, class 150, socket weld raised face type with drilled holes.		
5.	2 inch socket-weld flange.	10 nos.
6.	1.5 inch socket weld flange.	10 nos.
MS pipe carbon steel, schedule 40 IS standard.		
7.	2 inch MS pipe.	8 m
8.	1.5 inch MS pipe.	12 m
9.	1.5 inch MS pipe.	8000 mm