

## PUDUCHERRY POWER CORPORATION LIMITED (A GOVERNMENT OF PUDUCHERRY UNDERTAKING)



T.R. PATTINAM – 609606, KARAIKAL.

Fax: 04368 - 233355.

E-Mail: ppclmmc@gmail.com

Our GSTIN No.: 34AAACP6507E1ZS Dt.04.02.2025

Ref. No: AB-068/MMC/2024-25/2016

**ENQUIRY** 

11/02/2025

To

As per list enclosed.

Phone No:04368- 233060

Sub: Inviting offer for Steam Turbine Lube oil cooler tube Bundle

Assembling work as per the scope of work at PPCL Site, T.R.Pattinam, Karaikal - Reg.

**QUOTATION TO BE:** 

OUOTATION TO BE:	00 00DM
Submitted on or before 24.02.2025 – 12.00 PM	Opened on 25.02.2025 -03.00PM
Kept valid up to three months	Submitted in One Part

Wax Sealed quotations are invited for "Steam Turbine Lube oil cooler tube Bundle Assembling work as per the scope of work "at PPCL site, T.R.Pattinam, Karaikal.

### TERMS AND CONDITIONS:

- 1. The rate quoted should be inclusive of manpower, tools and tackles, etc. required for the works, GST, EPF & ESI charges and other charges as admissible.
- 2. 100% Payment will be made within 30 days from the date of receipt of your invoice after completion of work satisfactorily and approval of Engineer-in-charge and after submission of EPF/ESI, etc. documents. Otherwise 80% payment will be made after completion of work satisfactorily and approval of Engineer-in-charge and the balance 20% payment will be made after submission of necessary EPF & ESI, etc. documents.
- 3. The bill in triplicate along with advance stamped receipt should be sent to the undersigned for effecting payment.
- The contractor should submit the following:

#### For EPF:

To be generated from the EPF website for the specific month for the manpower deployed to PPCL and the same to be enclosed separately with a covering letter.

- i) Combined challan of account no. 01,02,10,21 & 22 with TRRN number.
- ii) EPF Electronic Challan cum Return (ECR)
- iii) EPF Clallan summery/ EPF TRRN details



# PUDUCHERRY POWER CORPORATION LIMITED (A GOVERNMENT OF PUDUCHERRY UNDERTAKING)

T.R. PATTINAM - 609606, KARAIKAL.

E-Mail: ppclmmc@gmail.com

Fax: 04368 - 233355.

भारत

Our GSTIN No.: 34AAACP6507E1ZS

Ref. No: AB-068/MMC/2024-25/ 2016

Dt.04.02.2025

**ENQUIRY PAGE NO. 2** 

11.02.2025

Phone No: 04368-233060

To be generated from the ESI website for the specific month for the manpower deployed to PPCL and the same to be enclosed separately with a covering letter.

ii) ESI monthly contribution- online challan status (Transaction details) i) ESI challan number

iii) ESI monthly contribution details (contractor wise) for the month of......

And other records to be submitted along with the above:

Copy of register of wages for the persons deployed to PPCL duly attested by the contractor. Copy of register of muster roll/attendance for the persons deployed to PPCL duly attested by the contractor.

Copy of payment proof for the persons deployed to PPCL through bank duly attested by the contractor.

In addition to the above as a mandatory, the proposed parties/manpower supply contractors have to obtain the FORM-III -Registration certificate under Pondicherry shops and Establishment Rules 1964 as a Employer of the Establishment to be permitted to employ persons under their firm and also obtain Labour License under the contract labour (Regulation & Abolition act. 1970 with the labour Department, Government of Puducherry, Karaikal.

- 5. ESI/EPF to be submitted in separate code and PPCL code shall not be given.
- 6. Necessary Gate pass should be obtained well before the commencement of work.
- 7. All the Safety Rules as per the Factory Act 1948, Puducherry Factory Rule and PPCL Safety structions to be strictly followed inside the plant area.
- 8. In case of any faulty workmanship in the scope of work, the tenderer must rectify the same. Otherwise the estimated amount will be deducted in your work bill.
- 9. Our GSTIN No.: 34AAACP6507E1ZS registered with Commercial Taxes Department, Puducherry.
- 10. Sealed quotation should be super scribed as QUOTATION / ENQUIRY NO. AB-068 "Steam Turbine Lube oil cooler tube Bundle Assembling work during the Annual maintenance DUE ON: 24.02.2025".
- 11. Applicable other charges, if any should be clearly mentioned as whether inclusive or exclusive. If not mentioned, it will be presumed that the rate quoted is inclusive of all taxes other charges.
- 12. The party should submit two copies of photographs of all the employees deployed in PPCL for the above work for gate pass purpose. The name & photo of the employees should be attested by the contractor.
- 13. The undersigned reserves all rights to accept/reject any or all the quotations without assigning any reasons thereof.
- 14. The work should be completed within 07 (Seven) days from the commencement of work during shutdown. The mobilization time of seven days shall be given.

15. The work should not be sub-let. Sub-contracting not permitted.

O/ EXECUTIVE ENGINEER (MECH)-PLANT

Page 2 of 4



# PUDUCHERRY POWER CORPORATION LIMITED (A GOVERNMENT OF PUDUCHERRY UNDERTAKING) T.R. PATTINAM – 609606, KARAIKAL.



Phone No:04368- 233060

E-Mail: ppclmmc@gmail.com

Fax: 04368 - 233355.

Ref. No: AB-068/MMC/2024-25/ 2016

Our GSTIN No.: 34AAACP6507E1ZS Dt.04.02.2025

11.02.2025

#### **ENQUIRY PAGE NO.03**

"Steam Turbine Lube oil cooler tube Bundle Assembling work "at PPCL

Sl.No.	Description	Amount
1	"Steam Turbine Lube oil cooler tube Bundle Assembling work (Scope of work as per the annexure enclosed)	in Rs.
	Gross Total Amount in Rs.	
	Transportation, Accommodation, Boarding and EPF & ESI Charges	Inclusive
	Sub Total	
	GST @ 18%	2 ,
	Net Total Amount in Rs.	
(Rupee	S	

Payment Terms: As per Terms & Condition - 2

Validity: 90 days

<u>Note</u>: 1) The rates to be quoted in all the columns of the above schedule and no columns should be left blank, if any column is left blank then the offered quotation will not be considered.

2) The quoted schedule should be affixed by the company seal and signed by the concerned authority.

Name of the Company:

Company seal with Signature:



Phone No:04368- 233060



T.R. PATTINAM - 609606, KARAIKAL.

E-Mail: ppelmmc@gmail.com

Fax: 04368 - 233355.

Our GSTIN No.: 34AAACP6507E1ZS

Dt.04.02.2025

Ref. No: AB-068/MMC/2024-25/2016

#### ANNEXURE

#### SCOPE OF WORK

# STEAM TURBINE LUB OIL COOLER (West Side) (1 No)

- Hydraulic/Pressure Checking of tube and shell up to test pressure as per the instruction of Engineer in charge. If any tube/shell leakages observed the same to be repaired as per the instruction of Engineer in charges.
- 2. Tube bundle to be re-fixed on its position.
- 3. Fixing of gasket and boxing up of the oil side and checking of oil teak.
- 4. Fixing of gasket and boxing up of the water side and checking of water leak.
- 5. Tightness checking of oil side. Tightness checking of waterside.
- 6. After charging of cooling water/oil if any leakages in the cooler that is to be rectified.

#### **CONTRACTOR SCOPE:**

- 1. The contractor should be responsible for the safety of their personnel & their equipment. Necessary PPE and other safety norms should be followed.
- Where ever required, necessary scaffolding with material has to be arranged by the contractor. All tools, tackles, manpower and consumables other than PPCL scope to be arranged by the contractor.
- 3. Cutting of gaskets for all coolers and condenser should be done by the contractor.
- 4. One site supervisor to be deputed to the site for early completion of work.

5. The party should visit the site before quoting the rate.

EXECUTIVE ENGINEER (MECH)-PLANT

gralstor